

CASH-WILLIAMS BUILDING

St. Elmo, Colorado

Contractor: Deep Roots Craftsmen

Project Supervisor: Craig Asher

Historic rehabilitation and stabilization of the Cash-Williams Building, including structural repairs, replacement of deteriorated framing and siding, selective reconstruction of missing historic elements, weatherproofing, and preservation of original historic fabric and character.

